


INTERGRANULAR CORROSION

(INTERGRANULAR ATTACK.. “IGA”)

Metals are usually “polycrystalline” . . . an assemblage of single-crystal grains separated by grain boundaries.



Grain boundary in a polycrystalline metal (two-dimensional representation).

The atoms in the grain boundaries are in a distorted lattice (i.e., disordered).

The higher energies of grain boundary atoms make them slightly more reactive than grains.


BUT: difference is NOT NOTICEABLE in general corrosion.

SOMETIMES . . . grain boundaries can become highly reactive:

- **by concentration of impurity atoms (e.g., Fe in Al has low solubility, segregates in grain boundaries which corrode more rapidly than grains, and intergranular attack results);**
- **by enrichment of an alloying element (e.g., Zn in brass);**
- **by depletion of an alloying element (e.g., Cr in SS).**

IGA (Intergranular Attack) in Austenitic SS (Stainless Steel)

What is austenite? Consider phase diagram for iron and carbon:



Fe-Fe₃ Phase Diagram. The lower-left corner receives prime attention in heat-treating of steels. (In calculations, 0.77 percent is commonly rounded to 0.8 percent.)

Nomenclature

- cast iron / CS $> 2\%C$ / $< 2\% C$;
- δ - iron (“ δ - ferrite” not to be confused with ferrite oxides).. is BCC
- α - iron (“ferrite”) is also BCC;
- carbide (“cementite”) is Fe_3C ;
- γ - iron (“austenite”) is FCC.

austenite

- is non-magnetic;
- is unstable below $727^\circ C$

decomposes on slow cooling to ferrite + pearlite if hypoeutectoid;


pearlite + eutectic if hypereutectoid

(N.B. “pearlite” is the lamellar mixture of ferrite and carbide that forms on cooling austenite of eutectoid composition . . . $0.8\% C$).

Pearlite. This microstructure is a lamella mixture of ferrite (lighter matrix) and carbide (darker). Pearlite forms from austenitic of eutectoid composition. Therefore, the amount and composition of pearlite are the same as those of eutectoid austenite.



Pearlite Formation. Carbon must diffuse from the eutectoid austenite (~0.8 percent) to form carbide (6.7 percent). The ferrite that is formed has negligible carbon.



AUSTENITE decomposes on rapid cooling below 727°C (i.e., “quenching”) to:

“**MARTENSITE**” - a metastable forced solution of C in ferrite that is very hard, has BCT (body-centered-tetragonal) structure.

N.B. IN STAINLESS STEELS, THE THREE MAJOR CARBON STEEL PHASES (FERRITE, AUSTENITE, MARTENSITE) CAN ALSO BE FORMED.

Also:

- “ferritic-austenitic” (“duplex”)
- “precipitation-hardened”.

Stability and mechanical/physical properties depend on combination of alloying elements.

austenite stabilizers: C, N, Mn, Ni, (q.v. Ni alloys);

ferrite stabilizers: Si, Cr, Mo, Nb (Columbium”- Cb - ugh!), Ti.

Selection of a steel/alloy for a particular application depends on mechanical or physical property considered to be most important.

Unified
Numbering
system

W. S. Stead
& W. S. E.

Chemical compositions of stainless steels

AISI type	UNS number	%C	%Cr	%Ni	% other elements	Remarks
Group I Martensitic chromium steels						
410	S 41000	0.15 max	11.5-13.5	—	—	Turbine blades, valve trim
416	S 41600	0.15 max	12-14	—	Se, Mo, or Zr	"Free" machining
420	S 42000	0.35-0.45	12-14	—	—	Cutlery
431	S 43100	0.2 max	15-17	1.25-2.5	—	Improved ductility
440A	S 44002	0.60-0.75	16-18	—	—	Very hard ; cutters
Group II Ferritic nonhardenable steels						
405	S 40500	0.08 max	11.5-14.5	0.5 max	0.1-0.3 Al	Al prevents hardenir
430	S 43000	0.12 max	14-18	0.5 max	—	Auto trim, tablewar
442	S 44200	0.25 max	18-23	0.5 max	—	Resists O and S at h
446	S 44600	0.20 max	23-27	0.5 max	0.25N max	temperatures
Group III Austenitic chromium-nickel steels						
201	S 20100	0.15 max	16-18	3.5-5.5	5.0-7.5 Mn 0.25N max	Mn substitute for N;
202	S 20200	0.15 max	17-19	4-6	7.5-10 Mn 0.25N max	Mn substitute for N;
301	S 30100	0.15 max	16-18	6-8	2 Mn max	Strain hardens
302	S 30200	0.15 max	17-19	8-10	2 Mn max	Architectural uses
302B	S 30215	0.15 max	17-19	8-10	2-3 Si	Si for high-temp. oxidation
304	S 30400	0.08 max	18-20	8-12	1 Si max	Continuous 18-8S
304L	S 30403	0.03 max	18-20	8-12	1 Si max	Very low carbon
308	S 30800	0.08 max	19-21	10-12	1 Si max	"High" 18-8
309	S 30900	0.2 max	22-24	12-15	1 Si max	25-12, heat resistant
309S	S 30908	0.08 max	22-24	12-15	1 Si max	Lower carbon
310	S 31000	0.25 max	24-26	19-22	1.5 Si max	25-20, heat resistant
310S	S 31008	0.08 max	24-26	19-22	1.5 Si max	Lower carbon
314	S 31400	0.25 max	23-26	19-22	1.5-3.0	Si for high-temp. oxidation
316	S 31600	0.10 max	16-18	10-14	2-3 Mo	18-8S Mo
316L	S 31603	0.03 max	16-18	10-14	2-3 Mo	Very low carbon
317	S 31700	0.08 max	18-20	11-14	3-4 Mo	Higher Mo
321	S 32100	0.08 max	17-19	8-11	Ti 4 x (C/min)	Ti stabilized
347	S 34700	0.08 max	17-19	9-13	Cb + Ta 10 x (C/min)	Cb stabilized
Alloy 20*	J 95150	0.07 max	29	20	3.25 Cu, 2.25 Mo	Best corrosion resis
Group IV Age-hardenable steels*						
322	—	0.07	17	7	0.07 Ti, 0.2 Al	
17-7PH†	S 17700	0.07	17	7	1.0 Al	
17-4PH†	S 17400	0.05	16.5	4.25	4.0 Cu	
14-8MoPH†	S 13800	0.05 max	14	8.5	2.5 Mo, 1% Al	
AM350†	S 35000	0.10	16.5	4.3	2.75 Mo	
CD4MCu†	—	0.03	25	5	3.0 Cu, 2.0 Mo	

*Typical compositions

†Commercial designations

‡Cast form only

Sensitization:

Cr is added to steels to make them “stainless”. The Cr-rich oxide film (based on Cr_2O_3) is thin, adherent and very protective.

BUT if heated into range 510-790°C, the steels “sensitize” and become prone to IGA.


Sensitization involves the precipitation of Cr carbide (Cr_{23}C_6) at the grain boundaries; at the high temperature its solubility is virtually zero.

The C diffuses readily, and the disorder in the boundaries provides nucleation sites.

This depletes the boundaries of Cr.

Sensitization (continued)

Diagrammatic representation
of a grain boundary in sensitized
type 304 stainless steel.



Electron photomicrograph of
carbides isolated from sensitized type
304 stainless steel.




Cross section of area shown above.


Sensitization by welding, or "Weld Decay"

During welding, the weld "bead" and the metal on either side pass through the temperature range for sensitization.


Temperature AND time are crucial for carbide precipitation: sensitized areas are on either side of the bead.



Tablecloth analogy of heat flow and temperatures during welding. The rise and fall of each stripe represents the rise and fall of temperature in a welded plate.



Location of thermocouples



(b)

time
within
correct
range ...

A	13s
B	12s
C	8½s
D	—

Temperatures during electric-arc welding of type 304 stainless steel.

sens.
range
should
be
here

Actual measurements made with thermocouples at points ABCD. Fontana says metal at and between points B and C within sensitizing range for some time.

Discuss

N.B. Sensitized SS can be used in many environments which are not too aggressive or where selective corrosion not a problem (domestic, architecture).

Minimizing IGA of SS

- (1) Heat Treatment "Quench - Annealing"**
- or ... "Solution - Annealing"**
- or "Solution - Quenching"**

Involves heating to above Cr carbide precipitation temperature to dissolve carbides, then water-quenching to cool through sensitization range rapidly.

Most austenitic SS supplied in solution-quenching condition; if welded during fabrication, must be quench-annealed to avoid weld decay during subsequent exposure to corrosive environments.

Solution-quenching of large components can be a problem.

Discuss: why not heat-treat just the weld region?


(2) Alloy “stabilization”

Elements that are strong carbide formers are added:

Nb (or Nb+Ta) \longrightarrow type 34 > SS

Ti \longrightarrow type 32 > SS

Important to ensure that Nb (for example) carbide has precipitated, so that Cr Carbide cannot precipitate and reduce corrosion resistance at grain boundaries (REMEMBER - it is the Cr that provides the corrosion resistance, not the stabilizer).



Schematic chart showing solution and precipitation reactions in type 304 and 347.

Stabilized SS from supplier usually heat-treated by quenching from ~1070°C.


- Nb carbide has precipitated,
- Cr left in solution, hence no C available for any reactions with Cr at lower temperatures.

HOWEVER, care is needed during welding etc.

If welding involves a rapid cooling of metal from temperatures just at or below the melting point (as can occur in thin sheets), BOTH Nb and Cr remain in solution.

This metal can now be sensitized if it is heated to the Cr carbide precipitation range (510 - 790°C, as might occur during a stress-relief).

“Knife-Line-Attack” (KLA) may now occur in narrow band next to weld if exposed to corrosive environment.




**Knife-line attack on
type 347 stainless steel.**

Should have been heat-treated between 790 & 1230 °C (Nb carbide precipitates, Cr dissolves).

(3) Use “Low-Carbon” (< 0.03%) Alloy.

At concentrations < 0.03%, not enough C can precipitate as Cr carbide to sensitize. Get “L-Grade” or “ELC” alloys e.g., “type 304L”.



Elimination of weld decay
by type 304L.

weld
bead
at back

N.B. Must take care to avoid C contamination during casting, welding, etc.

Other Alloys and IGA

Alloy with precipitated phases may also show IGA:

- Duralumin(um) Al-Cu can precipitate CuAl_2 and deplete Cu locally;
- Die-cast Zn alloys containing Al... IGA in steam, marine environments;
- Minor IGA effects in many Al alloys.